

Maryland Historical Trust State Historic Sites Inventory Form

Survey No. T-856

Magi No.

DOE ☐ yes ☐ no

1. Name (indicate preferred name)

historic

and/or common Jackson House

2. Location

street & number Route 33 and Mission Road ☐ not for publicationcity, town Tilghman ☐ vicinity of congressional district Fifth

state MD county Talbot

3. Classification

Category	Ownership	Status	Present Use
<input checked="" type="checkbox"/> district	<input checked="" type="checkbox"/> public	<input checked="" type="checkbox"/> occupied	<input type="checkbox"/> agriculture
<input checked="" type="checkbox"/> building(s)	<input type="checkbox"/> private	<input type="checkbox"/> unoccupied	<input type="checkbox"/> commercial
<input type="checkbox"/> structure	<input type="checkbox"/> both	<input type="checkbox"/> work in progress	<input type="checkbox"/> educational
<input type="checkbox"/> site	Public Acquisition	Accessible	<input type="checkbox"/> entertainment
<input type="checkbox"/> object	<input type="checkbox"/> in process	<input checked="" type="checkbox"/> yes: restricted	<input type="checkbox"/> government
	<input type="checkbox"/> being considered	<input type="checkbox"/> yes: unrestricted	<input type="checkbox"/> industrial
	<input checked="" type="checkbox"/> not applicable	<input type="checkbox"/> no	<input type="checkbox"/> military
			<input type="checkbox"/> museum
			<input checked="" type="checkbox"/> park
			<input type="checkbox"/> private residence
			<input type="checkbox"/> religious
			<input type="checkbox"/> scientific
			<input type="checkbox"/> transportation
			<input type="checkbox"/> other:

4. Owner of Property (give names and mailing addresses of all owners)

name Anne W. Ryan

street & number 1525 South George Mason telephone no.:

city, town Arlington state and zip code VA 22204

5. Location of Legal Description

courthouse, registry of deeds, etc. Talbot County Clerk of Court liber 591

street & number Talbot County Courthouse folio 281

city, town Easton state MD

6. Representation in Existing Historical Surveys

title

date ☐ federal ☐ state ☐ county ☐ local

depository for survey records

city, town state

7. Description

Survey No. T-856

Condition

☐ excellent
☒ good
☐ fair

☐ deteriorated
☐ ruins
☐ unexposed

Check one

☐ unaltered
☒ altered

Check one

☒ original site
☐ moved date of move _____

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The Jackson House is located on the southeast corner of Rt. 33 and Mission Road in the village of Tilghman on Tilghman Island, Talbot County, MD. The house faces west, with the principal gable oriented on a north/south axis.

Built between 1890-1900, this two-story, frame house is clad in weatherboard. The roof is covered in asphalt shingles and the foundation is low brick piers.

The west (main) elevation has five bays with a central door flanked by two two-over-two sash windows with wide surrounds. The door has a three light transom and sidelights. There is a full-width porch across the first floor supported by doric columns with a square post balustrade. The porch cornice has a sawtooth moulding and black and white striped awnings. The second floor is lit by five two-over-two sash windows with wide surrounds.

The south elevation is a two bay gable end with shallow cornice returns and pilaster cornerboards. There are two two-over-two sash windows on the first and second floors of this elevation and two square windows in the attic story. There is an interior, brick chimney at the south gable end. A two bay, two-story wing extends to the rear with a door and one two-over-two sash window on the first floor and two two-over-two sash windows on the second floor.

The five bay east (rear) elevation has a gable end wing which includes the two southern bays. This wing has pilaster cornerboards and two square windows at the attic story. An interior brick chimney rises above this eastern gable end. The first floor northern bays have an enclosed, shed roof addition with black and white striped awnings. Two two-over-two sash windows light the second story above this addition. The central bay of this five bay elevation is a two-story, projecting shed roof addition lit by two small two-over-two sash windows.

8. Significance

Survey No. T-856

Period	Areas of Significance—Check and justify below			
<input type="checkbox"/> prehistoric	<input type="checkbox"/> archeology-prehistoric	<input type="checkbox"/> community planning	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
<input type="checkbox"/> 1400–1499	<input type="checkbox"/> archeology-historic	<input type="checkbox"/> conservation	<input type="checkbox"/> law	<input type="checkbox"/> science
<input type="checkbox"/> 1500–1599	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> literature	<input type="checkbox"/> sculpture
<input type="checkbox"/> 1600–1699	<input checked="" type="checkbox"/> architecture	<input type="checkbox"/> education	<input type="checkbox"/> military	<input type="checkbox"/> social/
<input type="checkbox"/> 1700–1799	<input type="checkbox"/> art	<input type="checkbox"/> engineering	<input type="checkbox"/> music	<input type="checkbox"/> humanitarian
<input checked="" type="checkbox"/> 1800–1899	<input type="checkbox"/> commerce	<input type="checkbox"/> exploration/settlement	<input type="checkbox"/> philosophy	<input type="checkbox"/> theater
<input type="checkbox"/> 1900–	<input type="checkbox"/> communications	<input type="checkbox"/> industry	<input type="checkbox"/> politics/government	<input type="checkbox"/> transportation
		<input type="checkbox"/> invention		<input type="checkbox"/> other (specify)

Specific dates

Builder/Architect

check: Applicable Criteria: ☐ A ☐ B ☒ C ☐ D
and/or

Applicable Exception: ☐ A ☐ B ☐ C ☐ D ☐ E ☐ F ☐ G

Level of Significance: ☐ national ☐ state ☒ local

Prepare both a summary paragraph of significance and a general statement of history and support.

The Jackson House is a well preserved example of late 19th century architecture in the village of Tilghman. The classical detail of its doric front porch is unusual for Tilghman Island, although similar columns appear on the Birmingham house in Tilghman and the Weber house in Fairbank. The Jackson family is remembered as a former resident of this house.

Survey No. T-856

Acreage of nominated property _____

Quadrangle name _____

Quadrangle scale _____

UTM References do NOT complete UTM references

A

Zone Easting Northing

B


Zone Easting Northing

C



Diagram C illustrates the distribution of the number of active neurons. It shows three horizontal bars, each with vertical lines representing the frequency of a specific number of active neurons. The first bar has two vertical lines. The second bar has four vertical lines, with the third and fourth lines being thicker. The third bar has six vertical lines, with the fourth, fifth, and sixth lines being thicker. This indicates a shift in the distribution towards higher numbers of active neurons.

D

E 

F

G 

H

Verbal boundary description and justification

List all states and counties for properties overlapping state or county boundaries

state	code	county	code
-------	------	--------	------

state	code	county	code
-------	------	--------	------

<u>name/title</u>	Elizabeth Hughes, architectural historian
-------------------	---

organization Talbot County Planning Office **date** 8/90

street & number Talbot County Courthouse **telephone** 822-2030

city or town	Easton	state	MD
---------------------	--------	--------------	----

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.


return to: Maryland Historical Trust
Shaw House
21 State Circle
Annapolis, Maryland 21401
(301) 269-2438

Jackson House description continued.

The north elevation has two two-over-two sash windows on the first and second floors, and two square windows at the attic story. There is an interior brick chimney at this north gable end.

The interior was not seen.

T-856
Jackson House
Tilghman Island Quadrangle







T-856

Jackson House

T-856